

Dam ID: KA-0030  
Kaloko Reservoir

Inspection No: 2016-044  
Date: April 12, 2016

STATE OF HAWAII - DLNR  
DAM SAFETY INSPECTION SHEET

Inspection Type: Visual Dam Safety Inspection

Persons Present	Affiliation	Phone Number
<u>Ricky Cassiday</u>	<u>Lucas Trust Representative</u>	<u></u>
<u>Edwin Matsuda</u>	<u>DLNR</u>	<u></u>
<u>Denise Manuel</u>	<u>DLNR</u>	<u></u>
<u></u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>

Weather Condition: ☒ Rain previous day ☐ Rainy ☐ Drizzle / Mist ☐ Cloudy/Overcast ☒ Partly Cloudy ☐ Sunny ☐ Dry

Comments: 9:15 am

**1. General:** *(Information currently on file, update as required)*

Dam/Res. Name	<u>Kaloko Reservoir</u>	
Owner	<u>Mary N. Lucas Trust and Pflueger Properties</u>	
Owner Contact	<u>Ricky Cassiday / Jimmy Pflueger</u>	Owner Ph. <u></u>
Lessee	<u></u>	Lessee Ph. <u></u>
O & M Contractor	<u>KICO – Kilauea Irrigation Company – Tom Hitch</u>	O & M Ph. <u></u>
Nearest City	<u>Kilauea (2.6 Miles)</u>	Latitude <u>22.1781</u> ° (decimal)
County	<u>Kauai</u>	Longitude <u>-159.3798</u> ° (decimal)
Tax Map Key(s)	<u>(4) 5-1-002:001 – Owned by Pflueger Properties - Kauai TMK Property Search (Feb 2012)</u>	
	<u>(4) 5-1-002:005 – Owned by Mary N Lucas Trust - Kauai TMK Property Search (Feb 2012)</u>	

Dam Status	<u>Active</u>	Hazard Potential	<u>High</u>	Dam Size	<u>Intermediate</u>
Year Completed	<u>1890</u>	Dam Length	<u>915</u> ft.	Dam Height	<u>44 *</u> ft.
Normal Storage	<u>1255*</u> ac. ft.	Max. Storage	<u>1400*</u> ac. ft.	Max. Surface Area	<u>38 *</u> ac.
Offsite Drainage Area	<u>0.12</u> sq mi.	Spillway Type	<u>NONE</u>	Max. Spillway Q	<u>n/a</u> cfs

Owner owns land under dam facility: Yes

Emergency Action Plan on file with the Department: Yes

Reports on file with the Department:

- April 2011 - Ka Loko (KA-0030) - Phase II - Existing Conditions - AECOM
- November 2007 - Ka Loko (KA-0030) - Phase I Report - AECOM

\* Values are from before the dam breach

Dam ID: KA-0030Kaloko ReservoirInspection No: 2016-044Date: April 12, 2016**2. Questions for Owner's Rep.:**

	Yes	No	Unknown	Comments
Construction Plans Available	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Site / Facility Map	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Operation & Maintenance Manual	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<b>None on file</b>
Emergency Action Plan	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<b>Needs to be updated</b>
Modifications / Improvements	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Conduct Routine Inspections	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<b>Daily</b>
Conduct Routine Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<b>As needed / irrigation system being maintained/operated</b>
Vehicle access to site	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Not accessible <input type="checkbox"/> With Standard car <input checked="" type="checkbox"/> Requires 4-Wheel Drive
Access during heavy rains	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Not accessible <input type="checkbox"/> With Standard car <input checked="" type="checkbox"/> Requires 4-Wheel Drive
Access when spillway is flowing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Not accessible <input type="checkbox"/> With Standard car <input checked="" type="checkbox"/> Requires 4-Wheel Drive
Incident History	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/> Breached <input type="checkbox"/> Overtop <input type="checkbox"/> Slide <input type="checkbox"/> Down stream Flooding <input type="checkbox"/> Other: <b>Breach in March 2006</b>
Reservoir's Current Use	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sediment <input checked="" type="checkbox"/> Irrigation <input type="checkbox"/> Recreation <input type="checkbox"/> Flood Control <input type="checkbox"/> Drinking Water <input type="checkbox"/> Power Generation <input type="checkbox"/> Other: _____

**Findings and Corrective Actions:**

- ☒ a. The Owner shall maintain documentations including Construction plans, specifications, improvements, modifications, Operations and Maintenance Manuals and routine inspection logs for this dam facility.
- ☒ b. An Emergency Action Plan (EAP) is on file with the department, submit any updates as applicable.
- ☐ c. An EAP is required for High and Significant Hazard Dams. Submit an updated EAP for this facility.
- ☐ d. An EAP is recommended for all dams regardless of hazard class. Submit EAP if developed for the facility.
- ☒ e. Submit current Operations and Maintenance Manual or Procedures for this dam / reservoir facility.
- ☐ f. Submit Site or Facility Map of this Dam which identifies the location of major features including outlet works controls and conduits.
- ☐ g. Submit narrative and additional information detailing the improvements, modifications, and/or alterations at the dam site, unless covered by approved dam permit.
- ☒ h. Routine inspection logs were not inspected. **Start and maintain a log book**
- ☒ i. Dam owners shall provide for routine inspection of the dam.
- ☒ j. The dam did not appear to be maintained on a regular basis.
- ☐ k. Access to site appears to be satisfactory.
- ☐ l. There is no vehicular access to the dam site. Operational and emergency plans need to reflect this deficiency or access provided.
- ☒ m. Access to dam is questionable during severe weather conditions and/or spillway overflows. Operational plans and emergency plans need to reflect this deficiency or access provided.
- ☐ n. Provide a detailed narrative of the incident, responses taken, and any damages incurred. Dam owners are required to promptly advise the department of any sudden or unprecedented flood or unusual or alarming
- ☐ o. \_\_\_\_\_

**Additional Requirements:**

The following investigative study(s) are:

Required Recommended

- |                                     |                          |   |
|-------------------------------------|--------------------------|---|
| <input type="checkbox"/>            | <input type="checkbox"/> | Phase I Study   |
| <input type="checkbox"/>            | <input type="checkbox"/> | Hazard Classification   |
| <input type="checkbox"/>            | <input type="checkbox"/> | Emergency Action Plan (EAP)   |
| <input type="checkbox"/>            | <input type="checkbox"/> | Hydrology and Hydraulics (including Probable Maximum Flood and spillway capacity) |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | Seepage Analysis  |
| <input type="checkbox"/>            | <input type="checkbox"/> | Stability Analysis  |
| <input type="checkbox"/>            | <input type="checkbox"/> | Seismic Analysis  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | Other: <b>Post breach remediation</b>   |

Dam ID: KA-0030  
Kaloko Reservoir

Inspection No: 2016-044  
Date: April 12, 2016

**Physical Dam Features:** (Check All Applicable. Provide description of Items Observed and/or Take Photos. Indicate photo # in description.)

**3. Reservoir: Breach at 21.5 (reference EM-March 5, 2012)**

Level during inspection 19.97 ft per USGS Real Time Gage (gage / other)

Normal Operating Level/Range 19 to 21 ft per USGS Real Time Gage (gage / other)

Description: Level controlled by Kaloko Ditch diversion stoplogs

Typical Operation ☐ Spillway always flowing ☒ Kept within normal range ☐ Kept Empty ☐ Drained Daily ☐ Only filled by Storms

☐ Other: \_\_\_\_\_

Sinkhole in Res.: ☐ # Observed: \_\_\_\_\_ Size: \_\_\_\_\_ by \_\_\_\_\_ in. Deep ☐ Not Visible ☒ None Observed

Description: \_\_\_\_\_

Staff Gage: Description: USGS Real time gage and staff gage near outlet intake (numbers are not corresponding)

**Findings:**

- ☐ a. The reservoir was not inspected.
- ☐ b. Satisfactory – Expected to fulfill intended function – no corrective action required.
- ☒ c. Fair - Expected to fulfill intended function, but maintenance or other actions are recommended.
- ☐ d. Poor – May not fulfill intended function; maintenance, repairs, or other actions are necessary.
- ☐ e. Unsatisfactory – Is not expected to fulfill intended function; repair, replacement, or modification is necessary.
- ☐ f. Unknown – Not visible, not accessible, not inspected, or unable to determine based on the observation taken.

**Corrective Actions:**

- ☒ g. The staff gage needs maintenance and/or repair. Description: Provide reference and/or make numbers consistent between 2 measuring systems (confirm if "0" on staff gage = 20 on USGS gage)
- ☐ h. A staff gage was not observed at the reservoir. Provide some method of quantifying the water level.
- ☐ i. A sinkhole was observed in the upstream reservoir. Conduct additional investigations and monitoring to identify the cause, risk and appropriate action.

**4. Inflow Works Description:**

☒ Number of Inflows Three (1 - Inflow from Kaloko Ditch, 2 - Drainage area estimated to be 76 acres, 3 - Inflow from Moloaa Ditch via 8" PVC pipe [reported to be closed](photo 220))

☐ Inflow Culvert / Pipe

Size: \_\_\_\_\_ in. ☐ DIP ☐ Corrugated Metal ☐ PVC ☐ HDPE ☐ Concrete ☐ Other \_\_\_\_\_

Control: ☐ Gate ☐ Valve ☐ Flow can either be Shut off or Bypassed

From: ☐ Stream Diversion ☐ Pump ☐ Reservoir ☐ Other \_\_\_\_\_

☒ Inflow Ditch / Flume Throwaway control – ¼ mile upstream on ditch

Dimension: ~ 6-ft Wide and 8-ft Deep (Size x Depth) Shape Rectangular at Control

Surface: ☒ Dirt ☐ Wood ☐ Concrete ☐ Lined w/ \_\_\_\_\_

Control: ☒ Gate ☐ Valve ☒ Flow can either be Shut off or Bypassed

From: ☒ Stream Diversion ☐ Pump ☐ Reservoir ☐ Other Kaloko Ditch

**Findings:**

- ☐ a. The inflow works were not inspected.
- ☐ b. Satisfactory – Expected to fulfill intended function – no corrective action required.
- ☒ c. Fair - Expected to fulfill intended function, but maintenance or other actions are recommended.
- ☐ d. Poor – May not fulfill intended function; maintenance, repairs, or other actions are necessary.
- ☐ e. Unsatisfactory – Is not expected to fulfill intended function; repair, replacement, or modification is necessary.
- ☐ f. Unknown – Not visible, not accessible, not inspected, or unable to determine based on the observation taken.

**Corrective Actions:**

- ☒ g. The inflow works needs maintenance and/or repair. Description: Maintain suitable access to throw away control structure
- ☐ h. \_\_\_\_\_

**5. Upstream Slope:**

(Typical Slope  $\pm$  2 H : 1 V )

Slope Protection: ☒ None ☐ Dumped Rock ☐ Fitted Rip Rap ☐ Grouted Rip Rap ☐ Liner \_\_\_\_\_ ☐ Other: \_\_\_\_\_

☐ Defect in Protection: Description: \_\_\_\_\_

Erosion: ☐ Loose soil w/ little vegetation ☐ Rut (<6") ☐ Gully (>6" deep) ☐ Not Visible ☒ None Observed

Description: \_\_\_\_\_

Cracks: ☐ Parallel with crest ☐ Perpendicular to crest ☐ Slide visible ☒ Not Visible ☒ None Observed

Description: **Vegetation limited observations**

Sinkholes: ☐ # Observed: \_\_\_\_\_ Size: \_\_\_\_\_ and \_\_\_\_\_ Depth ☐ Not Visible ☒ None Observed

Description: \_\_\_\_\_

Vegetation: ☐ None ☐ Low Ground Cover ☒ Bushes or Tall Grass ☐ Trees # \_\_\_\_\_ ☐ <6" ☐ >6" & <20" ☐ >20"

Description: **Thick grasses**

**Findings:**

- ☐ a. The upstream slope was not inspected.
- ☐ b. Satisfactory – Expected to fulfill intended function – no corrective action required.
- ☐ c. Fair - Expected to fulfill intended function, but maintenance or other actions are recommended.
- ☐ d. Poor – May not fulfill intended function; maintenance, repairs, or other actions are necessary.
- ☒ e. Unsatisfactory – Is not expected to fulfill intended function; repair, replacement, or modification is necessary.
- ☐ f. Unknown – Not visible, not accessible, not inspected, or unable to determine based on the observation taken.

**Corrective Actions:**

- ☒ g. Slope protection needs maintenance or repair. Description: **Establish and maintain erosion control ground cover**
- ☐ h. Rut and/or Gully erosion was observed on the slope, which requires maintenance and/or repair.  
Description: \_\_\_\_\_
- ☐ i. A crack was observed on the slope, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.
- ☐ j. A sinkhole was observed on the slope, which requires further investigation to determine the underlining cause. Repair and monitor the area.
- ☒ k. The upstream slope was not visible due to ~~high grass and bush~~ vegetation. Clear ~~high~~ vegetation and maintain low to enable easy visual inspection.
- ☐ l. Tree(s) were observed on the dam embankment. Trees have been identified as the probable cause of piping failures, and can possibly cause severe damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. All repair work shall be accomplished as per the requirements of licensed geotechnical or civil engineer. Routinely monitor the damaged area for signs of settlement and seepage.
- ☐ m. \_\_\_\_\_

Dam ID: KA-0030

Kaloko Reservoir

Inspection No: 2016-044

Date: April 12, 2016

**6. Crest:**

Approximate Crest Width: 12 to 15-ft (varies in breach section)

Access: ☐ None ☐ Walking Path ☒ Roadway, Surface / Width / Usage: 10-ft / Grassed / Vehicle Access

Erosion: ☐ Loose soil w/ little vegetation ☐ Rut (<6") ☒ Gully (>6" deep) ☐ Not Visible ☐ None Observed

Description: Breach in embankment-about 161-ft wide at base and 228-ft wide at crest (photos 204, 205)

Cracks: ☒ Parallel with crest ☒ Perpendicular to crest ☐ Slide visible ☐ Not Visible ☐ None Observed

Description: Cracks at the end of downstream embankment remnants – unstable slopes

Sinkholes: ☐ \_\_\_\_\_ in. Wide x \_\_\_\_\_ in. Long x \_\_\_\_\_ in. Deep ☐ Not Visible ☒ None Observed

Description: \_\_\_\_\_

Vegetation: ☐ None ☒ Low Ground Cover ☐ Bushes or Tall Grass ☐ Trees # \_\_\_\_\_ ☐ <6" ☐ >6" & <20" ☐ >20"

Description: \_\_\_\_\_

**Findings:**

- ☐ a. The crest was not inspected.
- ☐ b. Satisfactory – Expected to fulfill intended function – no corrective action required.
- ☐ c. Fair - Expected to fulfill intended function, but maintenance or other actions are recommended.
- ☐ d. Poor – May not fulfill intended function; maintenance, repairs, or other actions are necessary.
- ☒ e. Unsatisfactory – Is not expected to fulfill intended function; repair, replacement, or modification is necessary.
- ☐ f. Unknown – Not visible, not accessible, not inspected, or unable to determine based on the observation taken.

**Corrective Actions:**

- ☐ g. Access along the crest was satisfactory.
- ☒ h. Access along the crest was not possible. Description: Entire crest at breach section not accessible
- ☐ i. Rut and/or Gully erosion was observed on the crest, which requires maintenance and/or repair.  
Description: \_\_\_\_\_
- ☐ j. A crack was observed on the crest, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.
- ☐ k. A sinkhole was observed on the crest, which requires further investigation to determine the underlining cause. Repair and monitor the area.
- ☒ l. Portions of the crest were not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☐ m. Tree(s) were observed on the dam embankment. Trees have been identified as the probable cause of piping failures, and can possibly cause severe damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. All repair work shall be accomplished as per the requirements of licensed geotechnical or civil engineer. Routinely monitor the damaged area for signs of settlement and seepage.
- ☒ n. Embankment remnants (downstream) have very steep end slopes and have been determined to be unstable (AECOM April 2011)

**7. Downstream Slope:**(Typical Slope  $\pm$  2 H : 1 V )Access: ☐ lower roadway along toe ☐ roadway to outlet works ☐ walkway to outlet works ☒ None ObservedSlope Protection: ☒ None ☐ Dumped Rock ☐ Rip Rap ☐ Grouted Rip Rap ☐ ConcreteErosion: ☐ Loose soil w/ little vegetation ☐ Rut (<6") ☒ Gully (>6" deep) ☐ Not Visible ☐ None ObservedDescription: Left side of embankment has been noted to have a large erosion hole(AECOM April 2011)Cracks: ☐ Parallel with crest ☐ Perpendicular to crest ☐ Slide visible ☒ Not Visible ☒ None ObservedDescription: Excessive vegetation limited observations and accessSinkholes: ☐ \_\_\_\_\_ in. Wide x \_\_\_\_\_ in. Long x \_\_\_\_\_ in. Deep ☒ Not Visible ☒ None ObservedDescription: Excessive vegetation limited observations and accessVegetation: ☐ None ☐ Low Ground Cover ☒ Bushes or Tall Grass ☒ Trees # 100+ ☒ <6" ☒ >6" & <20" ☒ >20"Description: Excessive vegetation on left, breach section and right downstream slope (photos 206, 207, 208)Seepage: Seep Spot Number 1☐ Green Vegetation ☐ Wet or Muddy Ground ☒ Ponding Water ☐ Not Visible ☐ None Observed☐ Flowing, Description: Excessive vegetation limited accessWater Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: \_\_\_\_\_Description: Ponded water on second (lower) bench, 4/16/14 and 4/12/16 (photos 206, 207)**Findings:**

- ☐ a. The downstream slope was not inspected.
- ☐ b. Satisfactory – Expected to fulfill intended function – no corrective action required.
- ☐ c. Fair - Expected to fulfill intended function, but maintenance or other actions are recommended.
- ☐ d. Poor – May not fulfill intended function; maintenance, repairs, or other actions are necessary.
- ☒ e. Unsatisfactory – Is not expected to fulfill intended function; repair, replacement, or modification is necessary.
- ☐ f. Unknown – Not visible, not accessible, not inspected, or unable to determine based on the observation taken.

**Corrective Actions:**

- ☒ g. Slope protection needs maintenance or repair. Description: Establish and maintain erosion control ground cover
- ☒ h. Rut and/or Gully erosion was observed on the slope, which requires maintenance and/or repair. Description: Remediate large erosion hole on the left remnant with suitable material
- ☐ i. A crack was observed on the slope, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.
- ☐ j. A sinkhole was observed on the slope, which requires further investigation to determine the underlining cause. Repair and monitor the area.
- ☒ k. The down stream slope was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☒ l. Tree(s) were observed on the dam embankment. Trees have been identified as the probable cause of piping failures, and can possibly cause severe damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. All repair work shall be accomplished as per the requirements of licensed geotechnical or civil engineer. Routinely monitor the damaged area for signs of settlement and seepage.
- ☒ m. Seepage/Ponding water was observed. Monitor and conduct further investigation to locate the source of water and extent of any possible hazardous or developing condition.
- ☐ n. Seepage was observed flowing and particles were observed to be removed by the flow. Take immediate action to stop the loss of soil from the embankment. Conduct further investigation to determine the underlining cause and take corrective action. Monitor the area.
- ☒ o. The slope was very steep, around a 1 to 1 slope, further study is required to verify slope stability.
- ☒ p. Reestablish access to the downstream slope and toe
- ☒ q. Embankment has been breached – breach needs to be stabilized

**8. Abutments:**

Erosion: ☐ Loose soil w/ little vegetation ☐ Rut (<6") ☐ Gully (>6" deep) ☐ Not Visible ☒ None Observed  
 Description: \_\_\_\_\_

Cracks: ☐ Parallel with crest ☐ Perpendicular to crest ☐ Slide visible ☐ Not Visible ☒ None Observed  
 Description: \_\_\_\_\_

Vegetation: ☒ None ☐ Low Ground Cover ☐ Bushes or Tall Grass ☒ Trees # ~20 ☐ <6" ☒ >6" & <20" ☐ >20"  
 Description: About 20 large trees on the Right Downstream Abutment. Unable to determine Left Abutment as downstream slope is too overgrown to inspect (photos 203, 204, 205)

Seepage: Seep Spot Number 1  
☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☒ Not Visible ☒ None Observed  
☐ Flowing, Description: \_\_\_\_\_  
 Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: \_\_\_\_\_  
 Description: \_\_\_\_\_

Seep Spot Number 2  
☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☒ Not Visible ☒ None Observed  
☐ Flowing, Description: \_\_\_\_\_  
 Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: \_\_\_\_\_  
 Description: \_\_\_\_\_

**Findings:**

- ☐ a. The abutments were not inspected.
- ☐ b. Satisfactory – Expected to fulfill intended function – no corrective action required.
- ☐ c. Fair - Expected to fulfill intended function, but maintenance or other actions are recommended.
- ☒ d. Poor – May not fulfill intended function; maintenance, repairs, or other actions are necessary.
- ☐ e. Unsatisfactory – Is not expected to fulfill intended function; repair, replacement, or modification is necessary.
- ☐ f. Unknown – Not visible, not accessible, not inspected, or unable to determine based on the observation taken.

**Corrective Actions:**

- ☒ g. Slope protection needs maintenance or repair. Description: Establish and maintain erosion control ground cover
- ☐ h. Rut and/or Gully erosion was observed, which requires maintenance and/or repair.  
Description: \_\_\_\_\_
- ☐ i. A crack was observed along the abutments, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.
- ☐ j. The abutment area was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☒ k. Tree(s) were observed on the dam embankment. Trees have been identified as the probable cause of piping failures, and can possibly cause severe damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. All repair work shall be accomplished as per the requirements of licensed geotechnical or civil engineer. Routinely monitor the damaged area for signs of settlement and seepage.
- ☐ l. Seepage/Ponding water was observed. Monitor and conduct further investigation to locate the source of water and extent of any possible hazardous or developing condition.
- ☐ m. Seepage was observed flowing and particles were observed to be removed by the flow. Take immediate action to stop the loss of soil from the embankment. Conduct further investigation to determine the underlining cause and take corrective action. Monitor the area.
- ☒ n. Reestablish access to abutments

**9. Toe:**

Erosion: ☐ Loose soil w/ little vegetation ☐ Rut (<6") ☐ Gully (>6" deep) ☒ Not Visible ☒ None Observed  
 Description: Excessive vegetation prohibited safe access

Cracks: ☐ Parallel with crest ☐ Perpendicular to crest ☐ Slide visible ☒ Not Visible ☒ None Observed  
 Description: Excessive vegetation prohibited safe access

Vegetation: ☐ None ☐ Low Ground Cover ☒ Bushes or Tall Grass ☒ Trees # 50 + ☒ <6" ☒ >6" & <20" ☒ >20"  
 Description: Excessive vegetation – high vegetation and trees (photos 206, 207, 208)

Seepage: Seep Spot Number 1  
☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☒ Not Visible ☒ None Observed  
☐ Flowing, Description: Excessive vegetation prohibited safe access  
 Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: \_\_\_\_\_  
 Description: \_\_\_\_\_

Seep Spot Number 2  
☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☒ Not Visible ☒ None Observed  
☐ Flowing, Description: Excessive vegetation prohibited safe access  
 Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: \_\_\_\_\_  
 Description: \_\_\_\_\_

**Findings:**

- ☒ a. The toe was not inspected.
- ☐ b. Satisfactory – Expected to fulfill intended function – no corrective action required.
- ☐ c. Fair - Expected to fulfill intended function, but maintenance or other actions are recommended.
- ☐ d. Poor – May not fulfill intended function; maintenance, repairs, or other actions are necessary.
- ☐ e. Unsatisfactory – Is not expected to fulfill intended function; repair, replacement, or modification is necessary.
- ☒ f. Unknown – Not visible, **not accessible, not inspected**, or unable to determine based on the observation taken.

**Corrective Actions:**

- ☒ g. Slope protection needs maintenance or repair. Description: Establish and maintain erosion control ground cover
- ☐ h. Rut and/or Gully erosion was observed, which requires maintenance and/or repair.  
Description: \_\_\_\_\_
- ☐ i. A crack was observed along the near the toe, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.
- ☒ j. The toe area was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☒ k. Tree(s) were observed on the dam embankment. Trees have been identified as the probable cause of piping failures, and can possibly cause severe damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. All repair work shall be accomplished as per the requirements of licensed geotechnical or civil engineer. Routinely monitor the damaged area for signs of settlement and seepage.
- ☐ l. Seepage/Ponding water was observed. Monitor and conduct further investigation to locate the source of water and extent of any possible hazardous or developing condition.
- ☐ m. Seepage was observed flowing and particles were observed to be removed by the flow. Take immediate action to stop the loss of soil from the embankment. Conduct further investigation to determine the underlining cause and take corrective action. Monitor the area.
- ☒ n. Reestablish access to the downstream slope and toe



**10. Outlet Works:**

Culvert / Pipe

Type / Size: Three 24-in PVC Puka Pipe Risers to a manifold near the Right Abutment – unknown grouting and tunnel entrance. The pipe daylights in a 5-ft x 5-ft tunnel beyond the Right Abutment. The PVC pipe at this point is 18-in and runs in the old ditch. The 18-in pipe has an 18-in butterfly valve and then continues to a thrust block. At the thrust block an 18-in PVC pipe tees off to the left (KICO) with an 18-in butterfly valve. Another 18-in line continues straight (Lucas) with an 18-in butterfly valve. And there is also an 8-in PVC pipe that branches off the thrust block and controlled by an 8-in butterfly valve (reported to be a drain line at the filter station) (photos 210, 211, 215, 216)

Culvert: ☐ Concrete ☐ Masonry ☐ unlined earth ☐ Other \_\_\_\_\_Pipe: ☐ DIP ☐ Corrugated Metal ☒ PVC ☐ HDPE ☐ Concrete ☐ Other \_\_\_\_\_Control Type: ☐ Gate ☒ Valve ☐ Other 18-in butterfly valves / 8-in butterfly drain valveLocation: ☐ Control on Upstream side ☒ Control on Downstream sideSeepage: ☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☐ Not Visible ☒ None Observed☐ Flowing, Description: \_\_\_\_\_Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: \_\_\_\_\_

Description: \_\_\_\_\_

**Findings:**

- ☒ a. The outlet works were not tested
- ☐ b. The outlet works were not inspected
- ☐ c. Satisfactory – Expected to fulfill intended function – no corrective action required.
- ☒ d. Fair - Expected to fulfill intended function, but maintenance or other actions are recommended.
- ☐ e. Poor – May not fulfill intended function; maintenance, repairs, or other actions are necessary.
- ☐ f. Unsatisfactory – Is not expected to fulfill intended function; repair, replacement, or modification is necessary.
- ☐ g. Unknown – Not visible, not accessible, not inspected, or unable to determine based on the observation taken.

**Corrective Actions:**

- ☐ h. Seepage/Ponding water was observed. Conduct further investigation to locate the source of water and extent of any possible hazardous or developing condition.
- ☐ i. Seepage was observed flowing and particles were observed to be removed by the flow. Take immediate action to stop the loss of soil. Conduct further investigation to determine the underlining cause and take corrective action. Monitor the area. Failures caused by seepage/piping along the outlet conduit are very common and are considered to be a dangerous situation.
- ☐ j. Were not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☒ k. Consider upstream control
- ☒ l. Verify operational condition of all valves. Confirm that the drain valve is functional.
- ☒ m. Investigate and document condition of tunnel entrance from puka pipes. Vault reported to have been grouted – unknown valve condition/status and needs to be evaluated

Dam ID: KA-0030

Kaloko Reservoir

Inspection No: 2016-044

Date: April 12, 2016

**11. Spillway:**

**NO SPILLWAY**

Type: ☒ None ☐ Culvert/Pipe ☐ Channel

Description: \_\_\_\_\_

Dimension: \_\_\_\_\_ ft. Invert elevation: \_\_\_\_\_ ft. per staff gage

Slope Protection: ☐ None ☐ Grass ☐ Dumped Rock ☐ Fitted Rip Rap ☐ Grouted Rip Rap ☐ Concrete

☐ Defect in Protection: Description: \_\_\_\_\_

Approach: ☐ Clear ☐ High Veg. ☐ Trees ☐ Other: \_\_\_\_\_

Erosion: ☐ Scour ☐ Gully ☐ Headcut ☐ Not Observed ☐ Other: \_\_\_\_\_

Description: \_\_\_\_\_

Vegetation: ☐ None ☐ Low Ground Cover ☐ Bushes or Tall Grass ☐ Trees # \_\_\_\_\_ ☐ <6" ☐ >6" & <20" ☐ >20"

Description: \_\_\_\_\_

***Findings:***

- ☐ a. The spillway was not inspected.
- ☐ b. Satisfactory – Expected to fulfill intended function – no corrective action required.
- ☐ c. Fair - Expected to fulfill intended function, but maintenance or other actions are recommended.
- ☐ d. Poor – May not fulfill intended function; maintenance, repairs, or other actions are necessary.
- ☒ e. Unsatisfactory – Is not expected to fulfill intended function; repair, replacement, or modification is necessary.
- ☐ f. Unknown – Not visible, not accessible, not inspected, or unable to determine based on the observation taken.

***Corrective Actions:***

- ☐ g. Slope protection needs maintenance or repair. Description: \_\_\_\_\_
- ☐ h. The spillway approach was blocked. Clear approach.
- ☐ i. Severe scour erosion was observed which requires maintenance and/or repair.  
Description: \_\_\_\_\_
- ☐ j. A headcut was observed downstream of the spillway. Corrective / mitigative action is required to prevent this problem from moving upstream.
- ☐ k. Trees are unacceptable in the spillway channel and approach. Take corrective action to address the woody vegetation problem and repair the damaged area.
- ☐ l. Unclear if spillway is adequately sized. Spillway should pass the probable maximum flood. Verify spillway capacity and take corrective action as required.
- ☒ m. **Design and construct a spillway to safely pass the Inflow Design Flood**

**12. Downstream Channel:**

Name: Breach section overflows to Wailapa Stream towards former Morita Reservoir

Downstream: ☐ Sump ☐ Open Area ☐ Un-Defined Drainage-way ☒ Defined Drainage-way ☐ Other \_\_\_\_\_

Items along Stream Bank: ☐ None ☒ Road ☒ Houses ☐ Town ☒ Not Inspected

Description: Morita Reservoir has been removed

***Findings:***

- ☒ a. The downstream channel was not inspected.
- ☐ b. Satisfactory – Expected to fulfill intended function – no corrective action required.
- ☐ c. Fair - Expected to fulfill intended function, but maintenance or other actions are recommended.
- ☐ d. Poor – May not fulfill intended function; maintenance, repairs, or other actions are necessary.
- ☐ e. Unsatisfactory – Is not expected to fulfill intended function; repair, replacement, or modification is necessary.
- ☒ f. Unknown – Not visible, not accessible, not inspected, or unable to determine based on the observation taken.

***Corrective Actions:***

- ☐ g. \_\_\_\_\_

Dam ID: KA-0030

Kaloko Reservoir

Inspection No: 2016-044

Date: April 12, 2016

**Additional Comments:**

---

**Access to the Kaloko Ditch throwaways needs to be continually maintained so that operations can reach them to control flows during inclement weather conditions.**

---

**The Crest, Upstream and Downstream Embankment remnants have been determined to be unstable (AECOM April 2011).**

---

**A Spillway needs to be designed and constructed to appropriately pass the Inflow Design Flood.**

---

**Ka Loko Reservoir and Kaloko Reservoir are names which have been used in various reports. Kaloko Reservoir was used in this report.**

---

**The Upstream Slope/crest may have been regraded since the AECOM April 2011 site visit and survey. An updated survey should be completed for future design purposes.**

---


**No substantial remediation has been done since the 2006 breach of this dam and reservoir. Remediation and stabilization are needed.**

---

**Limitations and Intent of this Dam Safety Inspection:**

This Dam Safety Inspection was conducted to assess the general overall condition of the reservoir/dam, identify visible deficiencies, and recommend areas of for monitoring, additional investigative studies and corrective actions. The inspection is based only on visible features/areas of the dam at the time of inspection. No assurance can be made regarding the dam's condition after this date. Subsequent adverse weather and other factors may affect the dam's condition. This inspection is not a formal phase I or phase II dam safety inspection and may not include a review or evaluation from each specialist of an inspection team, such as a geologists, civil, geotechnical, structural, or hydraulics engineer. The owner should verify the findings of this report and take corrective actions. The owner may submit to the State alternative corrective actions that are certified by a licensed professional engineer in the State of Hawaii experienced in the design and construction of dams. This inspection does not relieve the owner/operator from their responsibility to conduct routine inspections, maintenance, repairs, modifications, monitoring, documentation, and/or investigative studies. The inspection was conducted under the authority of the Hawaii Revised Statutes Chapter 179D, and Hawaii Administrative Rules, Title 13, Chapter 190, titled "Dams and Reservoirs". Questions regarding this inspection should be forwarded to the Hawaii State Dam Safety Program; DLNR Engineering Division; PO Box 373; Honolulu, Hawaii 96809; Ph. (808) 587-0236.

Revised: October 28, 2006 : August 3, 2009



## 1. General Information

a. State Dam ID	KA-0030
b. National ID	HI00030
c. Dam Name	KALOKO RESERVOIR
d. Other Name(s)	
e. Longitude / Latitude	-159.3798 / 22.1781
f. County / Island	Kauai / Kauai
g. Type of Dam	Earthen
h. Purpose	Irrigation
i. Completed / Last Modified	1890 / -
j. Nearest City / Town	Kilauea (2.6 miles)
k. Water Body Type	State Regulated Dam
l. Dam Height	27 ft
m. Dam Length	915 ft
n. Drainage Area	0.12 sq. miles / 77 acres
o. Size Classification	Intermediate

## 2. Owner Information

a. Name of Owner	Mary N. Lucas Trust (Cassiday); Mary N. Lucas Trust (Taylor); Pflueger Properties
b. TMK(s):	(4) 5-1-002:001, (4) 5-1-002:005

## 3. Hazard Potential Classification

a. Hazard Classification	High
b. Emergency Action Plan	Yes





Aerial Photo (07/12/2007)

#### 4. Reservoir

a. Normal Storage	1,255 ac-ft / 409 MG
b. Maximum Storage	1,400 ac-ft / 456 MG
c. Surface Area	38.0 acres

#### 5. Primary Spillway

a. Minimum Spillway Width	None Found
b. Spillway Length	
c. Spillway Type	
d. Protection	
e. Maximum Discharge	

#### 6. Primary Outlet Works

a. Works Type	Downstream Control
b. Maximum Discharge	
c. Size	18 Inch
d. Control Description	18 Inch PVC Pipe in Tunnel at Left Abutment

#### 7. Embankment

a. Type of Dam	Earthen
b. Minimum Crest Width	
c. Upstream Slope Grade	
d. Upstream Slope Protection	Vegetation
e. Downstream Slope Grade	
f. Downstream Slope Protection	Vegetation
g. Dam Height	27 ft
h. Dam Length	915 ft

#### 8. Inflow Works

Type	Name	Controlled	Size
Ditch	Kaloko Ditch	Yes	~ 6 Ft Wide by 8 Ft Deep at Gate
Ditch	Molooa Ditch	No	8 Inch PVC



Kalako Reservoir (KA-0030)  
dam from afar



Kaloko (201).JPG

Kalako Reservoir (KA-0030)  
view from right abutment



W 159.37977°  
N 22.17713°

Kaloko (203).JPG

12/Apr/16 9:23:48 AM

Kalako Reservoir (KA-0030)  
view of left abutment



W 159.37932°  
N 22.17789°

Kaloko (204).JPG

12/Apr/16 9:35:48 AM

Kalako Reservoir (KA-0030)  
view of breach from reservoir



W 159.37942°  
N 22.17819°

Kaloko (205).JPG

12/Apr/16 9:36:25 AM



Kalako Reservoir (KA-0030)  
ponding water in breach



W 159.37962°  
N 22.17812°

Kaloko (206).JPG

12/Apr/16 9:38:25 AM

Kalako Reservoir (KA-0030)  
ponding water in breach



W 159.37965°  
N 22.17815°

Kaloko (207).JPG

12/Apr/16 9:38:29 AM

Kalako Reservoir (KA-0030)  
trees in breach



W 159.37965°  
N 22.17815°

Kaloko (208).JPG

12/Apr/16 9:38:35 AM



staff gage

12/Apr/16 9:46:37 AM

Kaloko (209).JPG

W 159.37889°  
N 22.17853°



Kalako Reservoir (KA-0030)  
intake to outlet works



W 159.37874°  
N 22.17845°

Kaloko (210).JPG

12/Apr/16 9:47:54 AM

Kalako Reservoir (KA-0030)  
intake to outlet works



W 159.37894°  
N 22.17849°

Kaloko (211).JPG

12/Apr/16 9:48:11 AM

Kalako Reservoir (KA-0030)  
downstream slope to outlet works



W 159.37958°  
N 22.17892°

Kaloko (212).JPG

12/Apr/16 9:58:08 AM

Kalako Reservoir (KA-0030)  
downstream slope to outlet works



W 159.37923°  
N 22.17977°

Kaloko (213).JPG

12/Apr/16 10:04:57 AM



Kalako Reservoir (KA-0030)  
outlet tunnel



W 159.37927°  
N 22.17997°

Kaloko (214).JPG

12/Apr/16 10:05:28 AM

Kalako Reservoir (KA-0030)  
downstream outlet valves



W 159.37889°  
N 22.18006°

Kaloko (215).JPG

12/Apr/16 10:08:19 AM

Kalako Reservoir (KA-0030)  
downstream outlet valves



W 159.37933°  
N 22.17997°

Kaloko (216).JPG

12/Apr/16 10:08:28 AM

Kalako Reservoir (KA-0030)  
downstream access road to outlet



W 159.37974°  
N 22.18020°

Kaloko (217).JPG

12/Apr/16 10:09:39 AM



Kalako Reservoir (KA-0030)  
view from embankment



W 159.38058°  
N 22.18068°

Kaloko (218).JPG

12/Apr/16 10:12:36 AM

Kalako Reservoir (KA-0030)  
access road to Moloaa diversion



W 159.37671°  
N 22.17496°

Kaloko (219).JPG

12/Apr/16 10:28:40 AM

Kalako Reservoir (KA-0030)  
Moloaa diversion ditch



W 159.37694°  
N 22.17477°

Kaloko (220).JPG

12/Apr/16 10:32:35 AM

Kalako Reservoir (KA-0030)  
access road to Moloaa diversion



W 159.37715°  
N 22.17472°

Kaloko (221).JPG

12/Apr/16 10:35:51 AM



**Kalako Reservoir (KA-0030)**  
dosnstream view from crest - small reservoir on left side



W 159.37711°      Kaloko (223).JPG      12/Apr/16 10:44:05 AM  
N 22.17982°

**Kalako Reservoir (KA-0030)**  
downstream slope



W 159.37849°      Kaloko (224).JPG      12/Apr/16 10:48:19 AM  
N 22.17989°

**Kalako Reservoir (KA-0030)**  
tree on downstream slope



W 159.37849°      Kaloko (225).JPG      12/Apr/16 10:48:22 AM  
N 22.17989°

**Kalako Reservoir (KA-0030)**  
downstream toe - debris removed from dam



W 159.37758°      Kaloko (226).JPG      12/Apr/16 10:48:51 AM  
N 22.18039°



Kalako Reservoir (KA-0030)  
downstream toe - debris removed from dam



W 159.37758°  
N 22.18039°

Kaloko (227).JPG

12/Apr/16 10:48:54 AM

Kalako Reservoir (KA-0030)  
piping on downstream slope



W 159.37752°  
N 22.18053°

Kaloko (228).JPG

12/Apr/16 10:49:15 AM